



MANHEIM NEVADA 6600 AUCTION LANE NORTH LAS VEGAS, NV 89165 (702)730-1400

VEHICLE DETAILS - 2018 KIA FORTE LX

3KPFL4A77JE239557 Body Style: 4DSN Top Type: Hard Top Ext Color: WHITE- SWP Int Color: 88,651 BLK- WK Odometer: LAS VEGAS DIRECT 08/03/2023 Work Order: 1231753 Seller: Received Date:

Sale Number: Lane Number: Run Number:

Inspector: CSANICO 08/03/2023 InService Date: N/A



GRADING

AUTO LLC



Grade 3.9 Average

- MSRP-Not Available
- Engine Starts-Yes
- Drivable-Yes

*Process protected under U.S. Patent No. 8,230,362

VALUE ADDED OPTIONS

Auxiliary Audio Input

Back-Up Camera

Bluetooth Connection

Satellite Radio

VEHICLE INFORMATION

OPTIONS -

- 50 State Emissions
- A/C
- AM/FM Radio
- Automatic Headlights
- Bucket Seats
- Child Safety Locks
- Cloth Seats
- Cruise Control
- Driver Air Bag
- Driver Illuminated
- Vanity Mirr

- Driver Vanity Mirror
- Dual Air Bags
- Front Head Air Bag
- Front Side Air Bag
- Intermittent Wipers
- Pass-Through Rear Seat
- Passenger Äir Bag

Sensor

- Passenger Illuminated Vanity M
- Passenger Vanity Mirror
- Power Locks

- Power Mirrors
- Power Windows
- Pwr Steering
- Rear Bench Seat
- Rear Defrost
- Rear Head Air Bag
- Security System
- Side Air Bags
- Steering Wheel Audio

Control

Tilt Steering

- Tilt Steering Wheel
- Tire Inflator
- Tire Pressure Monitor

System

- Traction Control
- Transmission w/Dual Shift

Mode

- Trip Computer
- Variable Speed

Intermittent Wi

MECHANICAL

- 4 Cylinder Gas
- Automatic
- 4X2
- Anti-lock Brakes
- Automatic Transmission

Allov

2.0 L

Wheels:

TIRES AND WHEELS

	- ,			
Tire	Tread Depth	Brand	Size	
Left Front:	5/32"	Aspen	205/55R16	
Left Rear:	6/32"	Aspen	205/55R16	
Right Front:	5/32"	Aspen	205/55R16	
Right Rear:	6/32"	Aspen	205/55R16	

INTERIOR .

- Odometer D Digits Analog -Operable
- Int Odor: OK
- Cloth WK

Master Key - 1

OTHER

- Title State: NV
- Title Received Date: N/A

Spare:	N/A	N/A	N/A				
ADDITIONAL INFORMATION							
G/L,							

1/14/24, 10:52 AM DAMAGE SUMMARY AND ADDITIONAL IMAGES Cosmetic Conventional Paint and Body Not Required-[1 Items] **IMAGE DESCRIPTION** CONDITION **SEVERITY** RF Door Mult Dents/No Paint Dmg PDR/2 Paint and Body Requires Conventional Repair-[2 Items] **DESCRIPTION IMAGE** CONDITION **SEVERITY** Front Bumper Cover Curb Rash GR 12" Rear Bumper Cover Mult Dents/Paint Dmg 3 Previous Repair-[1 Items] **IMAGE DESCRIPTION** CONDITION SEVERITY Hood Prev Repair Buffable **A** Miscellaneous-[8 Items] **IMAGE DESCRIPTION** CONDITION **SEVERITY** Deck Lid Misaligned Repair Required LF Wheel Curb Rash 1" to 2" LR Wheel Curb Rash 1/2" to 1" Replacement Required Owners manuals Missing RF Wheel Curb Rash 5" to 6" RR Wheel Curb Rash 5" to 6" Warning - Maintenance On Unacceptable Warranty Books Missing Replacement Required Included Repairs fixed with Panel Repairs-[2 Items] **IMAGE DESCRIPTION** CONDITION **SEVERITY** Front Bumper Cover Prev Repair Buffable Rear Bumper Cover Prev Repair Buffable **IMAGE DESCRIPTION** CONDITION **SEVERITY** 0000 Picture# 1 Overall Picture

https://cgi.autovin.de/Client/Showlog/1758124

VIN: 3KPFL4A77JE239557, Work Order: 1231753